


**IMGING**

# INSPECTION REPORT



# Inspection Report Summary



## Property Information

Claim Number  
**Tile Damage Example**

Type of Loss  
**Hail**

Property Owner's First Name  
**N/A**


Property Owner's Last Name  
**N/A**

Property Owner's Phone Number  
**N/A**

## About This Report

Report Created  
**10/07/2020**

Assets  
**44**

 Added Photos  
**7**

 Annotations  
**3**

 Images With Confirmed Damage  
**34**

## General Information

Completed by  
**Alexeis Reyes**

Completed on  
**09/30/2020**

Inspect List Type  
**Inspect List**




PO001

Photo Added by Luke Kennard  
10/05/2020 6:14 PM EDT

Additional Notes

Luke Kennard  
10/06/2020 2:10 PM EDT  
Roof Material Photo



PO003


Confirmed Damage	Count
Cracked tile (beta)	1





## PO004

Confirmed Damage	Count
Cracked tile (beta)	1



## PO129

Photo Added by Luke Kennard  
10/05/2020 6:22 PM EDT

### Additional Notes

No additional notes have been added.





## PO005-1 HAIL

Annotated by Luke Kennard  
10/06/2020 2:13 PM EDT

### Additional Notes


Luke Kennard  
10/06/2020 2:13 PM EDT  
Cracked tile



## PO008

Confirmed Damage	Count
Cracked tile (beta)	1





PO130

Photo Added by Luke Kennard  
10/05/2020 6:22 PM EDT

Additional Notes

No additional notes have been added.




PO010-1 OTHER

Annotated by Luke Kennard  
10/06/2020 5:11 PM EDT

Additional Notes

Luke Kennard  
10/06/2020 5:11 PM EDT  
Slipping tile





PO012


Confirmed Damage	Count
Chipped corner (beta)	1



PO014

Confirmed Damage	Count
Cracked tile (beta)	1





## PO029

Confirmed Damage	Count
Cracked tile (beta)	3




## PO029-1 OTHER

Annotated by Luke Kennard  
10/06/2020 5:14 PM EDT

### Additional Notes

Luke Kennard  
10/06/2020 5:14 PM EDT  
Cracked tiles







## PO031


Confirmed Damage	Count
Chipped corner (beta)	2



## PO032

Confirmed Damage	Count
Cracked tile (beta)	1





PO065

Confirmed Damage	Count
Cracked tile (beta)	1
Creased Shingle (beta)	1



PO066

Confirmed Damage	Count
Cracked tile (beta)	3
Rust (beta)	1




## PO126

Photo Added by Luke Kennard  
10/05/2020 6:21 PM EDT

### Additional Notes


No additional notes have been added.



## PO044

Confirmed Damage	Count
Cracked tile (beta)	2
Missing Shingle	1
Rust (beta)	1





**PO045**

Confirmed Damage	Count
Chipped corner (beta)	1
Cracked tile (beta)	4
Loose Material	1



**PO035**


Confirmed Damage	Count
Chipped corner (beta)	2
Cracked tile (beta)	1
Rust (beta)	2





### PO040

Confirmed Damage	Count
Cracked tile (beta)	2



### PO046


Confirmed Damage	Count
Chipped corner (beta)	2





## PO051


Confirmed Damage	Count
Cracked tile (beta)	1



## PO059


Confirmed Damage	Count
Cracked tile (beta)	2





### PO053

Confirmed Damage	Count
Cracked tile (beta)	1
Loose Material	1



### PO054


Confirmed Damage	Count
Cracked tile (beta)	1





## PO058

Confirmed Damage	Count
Cracked tile (beta)	4




## PO062

Confirmed Damage	Count
Cracked tile (beta)	2







## PO067

Confirmed Damage	Count
Loose Material	1
Rust (beta)	1




## PO106

Photo Added by Luke Kennard  
10/05/2020 6:21 PM EDT

### Additional Notes


No additional notes have been added.





## PO070

Confirmed Damage	Count
Chipped corner (beta)	2
Cracked tile (beta)	5



## PO112

Photo Added by Luke Kennard  
10/05/2020 6:21 PM EDT

### Additional Notes


No additional notes have been added.





## PO071

Confirmed Damage	Count
Chipped corner (beta)	1



## PO073


Confirmed Damage	Count
Chipped corner (beta)	4
Cracked tile (beta)	3





## PO074


Confirmed Damage	Count
Cracked tile (beta)	3
Hail Hit	1



## PO075

Confirmed Damage	Count
Chipped corner (beta)	2
Cracked tile (beta)	2





**PO076**


Confirmed Damage	Count
Chipped corner (beta)	1
Cracked tile (beta)	3



**PO077**

Confirmed Damage	Count
Chipped corner (beta)	4
Cracked tile (beta)	1





**PO080**

Confirmed Damage	Count
Chipped corner (beta)	2
Cracked tile (beta)	1



**PO084**


Confirmed Damage	Count
Chipped corner (beta)	3
Cracked tile (beta)	4





### PO085

Confirmed Damage	Count
Chipped corner (beta)	3
Cracked tile (beta)	4



### PO087

Confirmed Damage	Count
Chipped corner (beta)	3
Cracked tile (beta)	4





## PO088

Confirmed Damage	Count
Chipped corner (beta)	2
Cracked tile (beta)	1



## PO152

Photo Added by Luke Kennard  
10/05/2020 6:22 PM EDT

### Additional Notes

No additional notes have been added.





# Flight Information




Photo Locations from Scan

## GENERAL INFO

**Pilot in Command**  
 Alexeis Reyes

**Drone ID Number**  
 1633G7L00SU018

**Scan Date**  
 09/30/2020

**Start Time**  
 1:29 PM EDT


**End Time**  
 2:36 PM EDT

**Total Flight Time**  
 00:56:18

## ALTITUDES

 **Full Subject Photo**  
 119 ft

 **Lawn Mower**  
 89 ft

 **Detailed Checks (while traveling)**  
 61 ft

 **Safe Height**  
 80 ft